

May 4, 2022

B. Braun Medical Inc.
824 12th Avenue
Bethlehem, PA 18018-0027
Telephone 610-691-5400
Fax: 610-997-4049

RE: Product Code SL-2010M2096 Dialog Streamline Label Change

Dear Valued B. Braun Customer,

B. Braun Medical Inc. is releasing Streamline bloodlines from a secondary manufacturing site beginning May 2022. This letter is to provide you with a summary of the changes and to make you aware that <u>no ordering changes need to be made on your part and the product is the same. If you order SL-2010M2096, you may get SL-2010M2096A and if you order SL-2010M2096A, you may receive SL-2010M2096.</u>

We will have a mix of the old label/box and the new label/box. The new label that you may see on the product will have an A at the end of the product code as indicated by the yellow arrow in the graphics below.

- Product Code SL-2010M2096: Current label and box you are currently ordering.
- Product Code SL-2010M2096A: New product label. The A only indicates it is from a different manufacturing site. The new label and box will look like the graphics below.

Saline line tag:



New Box: (No changes in quantity)



Please feel free to contact our customer service for any questions you may have at 1-800-848-2066.

Sincerely,

Lisa Hedin

Product Director, Avitum

B. Braun Medical Inc.