



Product Service

**Add value.
Inspire trust.**

TÜV SÜD Product Service GmbH · Ridlerstrasse 65 · 80339 Munich · Germany

B. Braun Medical Inc.
824 -Twelfth Avenua
Bethlehem, PA. 180185

USA

Your reference/letter of	Our reference/name	Tel. extension/Email	Email	Date	Page
	Stefan Miltschitzky	+49 89 5008 4414	Stefan.miltschitzky@tuvsud.com	2022-03-09	1 of 1

TO WHOM IT MAY CONCERN

Confirmation Recertification Audit performed in 2021;

EN ISO 13485:2016 certificate Q5 044904 0046 Rev. 00, valid until 2021-09-16

We confirm that the recertification audit, #72169733, has been performed between 2021-05-17 and 2021-05-20.

Based on the results of this audit, the audit team, recommended the continuation of certification.

This letter doesn't imply certification. Final review of the audit report and release of certificates are scheduled, but not completed.

Yours sincerely,

Dr. Stefan Miltschitzky

Department Manager / PS-MHS-NA1

Registered Office: Munich
Trade Register Munich HRB 85742
UniCredit Bank AG · BIC
HYVEDEMMXXX
IBAN DE13 7002 0270 0048 8522 11
VAT ID No. DE129484267
Information pursuant to § 2 [1] DL-InfoV
(Germany) at www.tuvsud.com/imprint

Supervisory Board:
Holger Lindner (Chairman)
Board of Management:
Walter Reithmaier (Sprecher/CEO)
Dr. Jens Butenandt, Managing Director
(CTO)
Patrick van Welij, Managing Director
(CFO)

Phone: +49 89 50084-747
www.tuvsud.com/ps
TUV[®]

TÜV SÜD Product Service GmbH
Munich Branch
Medical Devices
Ridlerstrasse 65
80339 Munich
Germany