



B. Braun Medical Inc.
824 Twelfth Avenue
Bethlehem, PA 18018
Telephone: 1-800-848-2066
Fax: 1-610-997-4049

March 22, 2022

RE: Avitum Update - Digital Board Version 4 Has Been Discontinued.

Dear Valued B. Braun Customer,

The Dialog Digital Board version 4, part number 3456074B, has been discontinued. The replacement for the version 4 Digital Board is Digital Board version 5. The part number is 34562141. The Digital Board version 5 requires a software version of 9.18 or higher and it is ***not*** compatible with 9.12 software.

If your machines currently have 9.12 software, we recommend that customers upgrade the machine to the current software version of 9.1E before a replacement of the Digital Board version 4 is needed. The Digital Board version 4 is compatible with ***all*** version.9.xx software versions.

To perform this upgrade you will need the Retrofit kit 9.1B (part number 34562274). This will have the required components needed for the hardware upgrade. You will also need the 9.1E software (77091E). This upgrade will take approximately 4 hours to complete.

For trained technicians, technical support is available via JIRA:
<https://jira.bbraun.com/servicedesk/customer/portal/23>

If you have any questions do not hesitate to contact our Technical Service Team at 1-800-621-0445.

Kind regards,

Lisa Hedin
Product Director, Avitum